

# The Alton Mill:

One Building's Return to Use A Community Revived






## The Alton Mill:

One Building's Return to Use-A Community Revived

**Property Owners** 

Jordan and Jeremy Grant Alton Mill Development Incorporated














NASMITH ARCHITECT















### **Challenges:**

- •Few financial incentives
  - •Canada's tax system favours new construction
  - •Conventional financing unavailable
- •Located in a flood plain, limiting possible uses
- •Fish habitat issues
- •Building code issues
- •Water/moisture damage
- •Contamination, mildew, animal droppings
- •Parking and other site plan standards





#### **Rehabilitation Funding:**

Canadian Historic Properties Incentive Funds and,

Rural Economic Development Fund (Provincial)

Private Investment, Seaton Group, Alton Development Inc.

#### **Project Standards:**

Undertaken to the Standards and Guidelines for Conservation of Historic Places in Canada, as a Rehabilitation

Ontario Building Code provides considerable latitude to deal with historic conditions, particularly through the use of Part 11, as interpreted by the Chief Building Official

































### **Prohibitive - Not Impossible - to Repair**

**Timber Repairs in Progress** 


- Similar cost to rehabilitate existing space or to build new
- \$200.00/ s.f./costs in labour























CATHERINE NASMITH ARCHITECT





















N A S M I T H ARCHITECT











